Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	0	vehicle and (failure or abnormal or malfunction)and CAN and (multiplex same communincation same line)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/04/05 09:53
L2	0	vehicle and (failure or abnormal or malfunction)and CAN and (multiplex same communincation)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/04/05 09:53
L3	116505	vehicle and (failure or abnormal or malfunction)and CAN	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/04/05 09:53
L4	2401	vehicle and (failure or abnormal or malfunction)and CAN and multiplex	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/04/05 10:51
L5	240561	(short near6 circuit)or (disconnect\$5 same bus same communication)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/04/05 09:54
L6	221	4 and 5	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/04/05 09:54
L7	720	(resistance same value)and (ohm adj meter)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/04/05 09:55
L8	1	6 and 7	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/04/05 09:55

			ı			
L9	1	4 and 7	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/04/05 09:55
L10	392623	(resistance same value)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/04/05 09:55
L11	69	6 and 10	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/04/05 10:02
L12	204	(diagnos\$6 near6 trouble near6 code)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/04/05 10:13
L13	1	6 and 12	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/04/05 09:56
L14	7	4 and 12	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/04/05 09:56
L15	935	abnormality near6 code	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/04/05 09:59
L16	2	6 and 15	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR .	ON	2005/04/05 09:59
L17	6	("3732541" "4070648" "4456997" "4541095" "4959836" "5666381"). PN. OR ("6091711").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2005/04/05 09:59

L18	469	(diagnos\$6 same trouble same code)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/04/05 10:52
L19		10 and 18	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/04/05 10:14
L20	531	vehicle and (failure or abnormal or malfunction)and CAN and (multiplex same communication)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/04/05 10:51
L21	50	10 and 20	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/04/05 10:52
L22	7	15 and 20	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/04/05 10:52
L23	6473	(diagnos\$6 same trouble same code)or (abnormal\$5 same code)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/04/05 10:52
L24	41	20 and 23	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/04/05 11:05
L25	9	10 and 24	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR .	ON	2005/04/05 10:52
L26	19	("3967058" "4575860" "4809304" "4972408" "5086427" "5121386" "5268937" "5315299" "5329525" "5390185").PN. OR ("5600634").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2005/04/05 10:57

			1		000	
L27	2046	multiplex and ((main or branch)same communication same line)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/04/05 11:06
L28	157	10 and 27	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/04/05 11:11
L29	12	20 and 28	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/04/05 11:08
L30	52	23 and 27	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/04/05 11:08
L31	2	18 and 28	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/04/05 11:12
L32	8718	(vehicle same communication same network)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/04/05 11:12
L33	230	4 and 32	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/04/05 11:12
,L34	27	27 and 33	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/04/05 11:12